



SITE: IDEAL COOPERAGE
DATE: MAY 7-9, 1991
PHOTOS BY: P. DI PASCA (TAT)
DESCRIPTION: FIRST WEEK OF
SITE ACTIVITY



SITE: Ideal Cooperage, Jersey City, NJ

DATE: 05/07/91 PHOTO BY: P. Di Pasca

DESCRIPTION: Personnel from (l to r):

JCDOE, The Jersey Journal

(2 people), EPA-RAB, EPA-OEP

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/07/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Removal of guard rail from
entrance to site

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/07/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Removal of guard rail from
entrance to site

MAY 1991

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/07/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Removal of guard rail from
entrance to site

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/07/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Removal of guard rail from
entrance to site

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ

DATE: 05/07/91 PHOTO BY: P. Di Pasca

DESCRIPTION: Personnel from (l to r):

JCDOE, The Jersey Journal

(2 people), EPA-RAB, EPA-OEP

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Delivery of track loader

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Installation of new
front gate

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Name, address and phone
number of fence
contractor

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Initial conditions of site -
north end

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Initial conditions of site -
west side

1661 / 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Track loader used for
clearing of debris and drum
restaging

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Clearing of non-hazardous
debris with track loader

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Delivery of road stone for
entrance to site
(1st load)

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Name, address and phone number
of road stone supplier

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Delivery of road stone for
entrance to site
(2nd load)

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Delivery of track loader

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Installation of new
front gate

MAY 1991

A photograph of a dark green pickup truck, likely a Chevrolet Sierra, parked outdoors. The truck has a white door handle and a white door hinge. The side of the door features a "SIERRA 3500" badge and a large yellow decal for "Academy Fence". The decal includes the company name in a stylized font, the location "Orange, N.J.", and the phone number "731-0854". The truck is parked next to a wooden structure, possibly a fence or a building, and there is some grass and dirt visible in the foreground.

SIERRA 3500

Academy Fence
Orange, N.J.
731-0854

SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Name, address and phone
number of fence
contractor



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Initial conditions of site -
north end

IAV 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Initial conditions of site -
west side

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Track loader used for
clearing of debris and drum
restaging

1661 A



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Clearing of non-hazardous
debris with track loader

MAY 1991

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Delivery of road stone for
entrance to site
(1st load)

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Name, address and phone number
of road stone supplier

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Delivery of road stone for
entrance to site
(2nd load)

AY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Aerial view of initial
conditions - south end of site

1661 V 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: View of New York City
from hill above site

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Aerial view of initial
conditions - north end of site

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Spreading of road stone
with track loader

1A V 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Restaging of empty drums
with track loader

AV 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Restaging of empty drums
with track loader

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Pile of empty drums before
restaging into rows

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Aerial view of central
section of site during
empty drum restaging

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Aerial view of initial
conditions - south end of site

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: View of New York City
from hill above site

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ

DATE: 05/08/91 PHOTO BY: P. Di Pasca

DESCRIPTION: Aerial view of initial
conditions - north end of site

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Spreading of road stone
with track loader

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Restaging of empty drums
with track loader

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Restaging of empty drums
with track loader

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Pile of empty drums before
restaging into rows

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/08/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Aerial view of central
section of site during
empty drum restaging

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/09/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Clearing of non-hazardous
debris with track loader

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/09/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Clearing of non-hazardous
debris with track loader

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/09/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Clearing of non-hazardous
debris with track loader

MAY 1991



SITE: Ideal Cooperage, Jersey City, NJ
DATE: 05/09/91 PHOTO BY: P. Di Pasca
DESCRIPTION: Clearing of non-hazardous
debris with track loader

MAY 1991